

Report ID: 19,486,769 Version: 1 13 May 2019 Created:

Make:	Mitsubishi	Model:	Pajero	Body Style:	Wagon		Pass	Fail	N/A
Year:	1993	Registration:	DSM189	Reg Expiry:	23 Jul 2019	Engine			
WoF Expiry:		Odometer:	331,305 Kms	Good No:	19486769	Oil level	~		
VIN:	7A8CJ080702061089	Next Service:	551,505 Kills	Service Histor		Smoke & fumes	~		
	11005000702001005					Performance	~		
	port is not a warranty		· · · ·			Noise	~		
	a guide only. Considesting undertaken. The					Cooling System	•		<u> </u>
	ical inspection prior to					Coolant condition	~		
						Performance	~		<u> </u>
Key:	S P SC	-0	S P SC S P SC		S SC	Radiator / Hoses (visual)	~		
S = scratch	Sec	10		10c	*	Transmission	V		
D = dent	s sc			The	BIDSDC	Operation			<u> </u>
R = rust				10		Noise	~ ~		
PT = paint def C = crack	ect 1			+	SC	Clutch	~		
C = Crack P = pin dent	LHC	KI		-	JIII —				~
* = decals	s sc w				SD SC	CV joints	~		
SC = stone chi	ps VE			10		Wheel bearings	~		
W = significant scuffs S SC S S D SC S P SC S P SC						Brakes			T
						Performance	~		<u> </u>
<u>Body Ins</u>	pection Comments	Note: son	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		<u> </u>
						Tyres (lowest observed tread depth of tyres)			
						Left front		2	mm
						Right front		5	mm
						Left rear	(5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,minor surface rust ur	nderneath body ,				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
luctorian C	·					Operation		~	
Interior Comments drivers seat ripped, wear and tear ,						Electrical / Accessories			
Seats	drivers sea	at ripped,wear ar	id tear ,			Head lights	~		
Carpote	wear and	tear,worn ,				Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Squeaky no	bise coming from belts,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	1	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							I	I	
Inspecte	d by: Donovan Matar	а				Date: 13 May 20)19		

I have read and understood this condition guide.

Name:

Signature: