

Report ID: 19,487,238 Version: 1 14 May 2019 Created:

Make:	Nissan	Model:	Elgrand	Body Style:	SUV		Pass	Fail	N/A
Year:	2004	Registration:	HDN833	<b>Reg Expiry:</b>	03 Aug 2019	Engine			
WoF Expiry:	29 Mar 2020	Odometer:	136,373 Kms	Good No:	19487238	Oil level	~		
VIN:	7AT0DH6MX1310340(	Next Service:	138300	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
	W					Performance	~		
Key:		-0		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		1
D = dent R = rust	PTW DIS	1		710	HILDW	Operation	~		
PT = paint def	ect NP	r I		$\left( \left  \left( \right) \right\rangle \right)$	70141	Noise	~		
C = crack					S D SC	Clutch			~
P = pin dent	HIP				7414	CV joints			~
* = decals	sc 916			- John		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	t scuffs W				D	Performance	~		
Body Incr	pection Commonts	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Stone chips front screen. Jack compartment lid missing.						Tyres (lowest observed tread	d depth	of tyre	es)
Store emps none serven, sack comparation in missing.									mm
						Right front		5	mm
						Left rear		7	mm
Conditio	os During Body Insi	nection:	Dry			Right rear		3	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		r	
						Number of keys	1	I	I
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
			ر بر الع 			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		ŀ
							· ·		
Inspected by: Brian Hill Date: 14 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....