

Report ID: 19,488,137 Version: 2 21 May 2019 Created:

Signature: .....

Make:	Nissan	Model:	NV200	Body Style:	Van		Pass	Fail	N/A
Year:	2009	<b>Registration:</b>	LRW988	Reg Expiry:	09 Apr 2020	Engine	1	I	1
WoF Expiry:	23 Oct 2019	Odometer:	119,903 Kms	Good No:	19488137	Oil level	~		
VIN:	7AT0DH19X18000166	Next Service:	129900	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
					W	Performance	~		
Key:		-0		-01-	V	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	sc di			715	HIL	Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HID				거네	CV joints	~		
* = decals	- Alf			-No-	AD w	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Bodylog		Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front 5.0			
						Right front	-	.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry							Spare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Nice tidy 7 seater people moving van.						Window winder RR			~
Small tip, ja	ck & tools under front le	eft seat.				Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		·
									1
Inspecte	d by: Daryll Timms					Date: 16 May 20	19		

I have read and understood this condition guide.

Name: .....