

Guide	Version:
	Created:
	Pag

Make:	Volkswagen	Model:	Bora	Body Style:	Sedan		Pass	Fail	N/A
Year:	2000	Registration:	EYT459	Reg Expiry:	31 Aug 2019	Engine			
WoF Expiry:	01 Sep 2019	Odometer:	243,402 Kms	Good No:	19489109	Oil level		~	
VIN:	WVWZZZ1JZYW53212	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise		~	
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged to	r an additional o	narge.	Coolant condition	~		
	SC		S S S S C		S SC	Performance	~		
Key:	Bell	-0	3 330		330	Radiator / Hoses (visual)	~		
S = scratch	ATE			NOG	Tan	Transmission			
D = dent R = rust	s sc			715	S D SC	Operation	~		
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	s sc 916				ALC'S	Wheel bearings	~		
SC = stone chips					Brakes	I			
W = significan	s SC S		S SC S SC		S SC	Performance	~		
Body Incr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread	l depth	of tyre	es)
Minor stone chips in the windscreen ,							mm		
						Right front		5	mm
						Left rear		3	mm
Condition	ns During Body Insi	oection [.]	Dry			Right rear		3	mm
Conditions During Body Inspection: Dry			Spare	Yes					
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
Minor oil le	ak,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation		~	
Interior C	omments					Electrical / Accessories			
Seats	Average					Head lights		~	
	Average					Tail lights	~	-	
Carpets	Average					Indicators	~		$\left - \right $
Panels	Average					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		<u> </u>
						Window winder FR	~		+
General C	<u>Comments</u>					Window winder RL	~		
Done the test drive went 15 ks no for seen problems with the car did drive ok for the ks but did have a slight			Window winder RR	~					
ticking nois	e nothing bad i don't th	ink,a slight shuc	lder when idling ,			Rear view mirrors	~		
						Radio (basic test only)	~		
					CD (basic test only)	•		~	
					Number of keys	1		<u> </u>	
				~					
			Dry			Remote locking	~		$\left - \right $
Engine Timing Mechanism: Unknown Sat. Nav. (basic test only)					~				
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera					~				
Inspected by: Donovan Matara Date: 15 May 2019									

I have read and understood this condition guide.

Name:

Signature: