

Basic Vehicle Condition Guide

Report ID: 19,489,973


Version: 1

Created: 15 Jun 2019

Make: Model: Mercedes-Benz E350 **Body Style:** Sedan Year: 2010 Registration: MCJ411 Reg Expiry: 01 Dec 2019 WoF Expiry: **Odometer: Good No:** 17 May 2020 77,940 Kms 19489973 VIN: WDD2073562F070363 **Next Service:** 85,000kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Wet

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive

Interior Comment	<u>'S</u>
Seats	Good
Carpets	Good
Panels	Average
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Ca Thach Date: 15 Jun 2019

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
		~
~		
	l	
~		
~		
Tyres (lowest observed tread depth		
7	7	mm
7		mm
7	7	mm
7		mm
Yes		
~		
/		1
\(\triangle \)		
<i>V</i>		
V V V V V V		
V V V V V V		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V 1		
V V V V V V V V V V V V V V V V V V V		
	V V V V V depth	v v v v v v depth of tyre 7 7 7 7 Yes

Signature: