

Basic Vehicle Condition Guide

Report ID: 19,490,039


Version: 2

Created: 25 Jun 2019

Make: Model: Nissan Primera **Body Style:** Sedan Year: 2001 Registration: FPE877 Reg Expiry: 19 Apr 2020 WoF Expiry: **Odometer:** 01 Nov 2019 148,080 Kms **Good No:** 19490039 VIN: 7AT0DH2GX10000929 **Next Service:** 158085 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Wiper mark and stone chips front screen. Right sill needs painting.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Brian Hill Date: 15 May 2019

Name:

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>y y</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ' | | |
| Noise | > | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | es) |
| Left front | 3 | .0 | mm |
| Right front | 3 | .0 | mm |
| Left rear | 5.0 | | mm |
| Right rear | 5.0 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | \(\times \) | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ' | | |
| Tail lights | ~ | | |
| Indicators | ' | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | V V V V V V V V V V V V V V V V V V V | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | V | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ' |

Signature: