

Report ID: 52,146 Version: 1 13 Jun 2019 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	KNH104	Reg Expiry:	10 Dec 2019	Engine			<u> </u>
WoF Expiry:		Odometer:	146,534 Kms	Good No:	19490307	Oil level	~		
VIN:	WBAVA72040KX20184	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
		_				Performance	~ ~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch							ransmission		
D = dent									1
R = rust				10		· · · · · · · · · · · · · · · · · · ·	v		
PT = paint def	ect					Noise	~		<u> </u>
C = crack P = pin dent	LHC				االلا	Clutch			~
* = decals						CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs						Brakes		1	1
					Level in the P	Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		<u> </u>
R/R window not working						Tyres (lowest observed tread depth of tyres)			
						Left front		3	mm
						Right front	:	3	mm
						Left rear	3	.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		
					Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leaks						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Brakes shud	lder					Window winder RR		~	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	•	*
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: J Ottesen Date: 22 May 2019									

I have read and understood this condition guide.

Name:

Signature: