

Report ID: 19,490,353 Version: 2 17 May 2019 Created:

Make:	Holden	Model:	Rodeo 4X2	Body Style:	Utility		Pass	Fail	N/A
Year:	2004	Registration:	CEZ914	Reg Expiry:	23 Jun 2019	Engine			L
WoF Expiry:	30 Aug 2019	Odometer:	270,234 Kms	Good No:	19490353	Oil level	~		
VIN:	MPATFR77H4H53726	Next Service:	275,555	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		SC SC		SC	Performance	~		
Key:	B	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc d			710	HIV	Operation	~		
PT = paint defe	ect NP				101h	Noise	~		
C = crack						Clutch	~		
P = pin dent	sc dR				74116	CV joints	~		
* = decals				10	S SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
		e	S SC		S SC	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Radio antenna broken						Tyres (lowest observed tread	l depth	of tyre	es)
						Left front	5.	8	mm
						Right front	6.	4	mm
						Left rear	7.	9	mm
Conditions During Body Inspection: Dry						Right rear	6.1 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil leak Gear box oil leak						Suspension performance	~		
Gear box or	Геак					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
	- <u>.</u>					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicmy Timing Chain						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ian Dunn Date: 17 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....