

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance S SC S S D SC SDSC S D SC Key: Radiator / Hoses (visual) V < S = scratch Fransmission D = dent S SC Operation V R = rustNoise V PT = paint defect SC C = crackClutch V P = pin dent CV joints ~ S D SC \* = decals ς Wheel bearings V SC = stone chips Brakes W = significant scuffs S SC S SC S P SC Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 3 **Right front** 5 mm Left rear 7 mm **Right rear** 6 mm Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Average Head lights Seats 1 Tail lights ~ Average Carpets Indicators ~ middle console worn, Dashboard warning lights 1 Panels V Wipers (front & rear) Average Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 1 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism:** Cambelt Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Kms: No Reversing camera ~

Inspected by: Donovan Matara

16 May 2019 Date:

I have read and understood this condition guide.

Name: .....

Signature: .....

Report ID: 19,490,686 1

Version:

Pass

~

V

V

V

Oil level

Noise

Smoke & fumes

Performance

16 May 2019 Created:

Fail

N/A