



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,490,981
Version:	2
Created:	09 Sep 2019

Make:	Nissan	Body Style:	Hatchback
Model:	Note	VIN:	7AT0DH79X19027472
Year:	2017	Odometer:	85,517 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	3.0	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>3.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	3.0	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>4.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	4.0	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>5.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	5.0	mm	89	L/H Doors	Good		
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	N/A	66	Tools	✓	90	R/H Doors	Good
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	68	Heater Fan	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	70	Horn	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	•	72	Sun Visors	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td>	74	Seats	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓</th> <th colspan="2">Interior</th> <td>75</td> <td>Carpets</td> <td>Average</td>	46	Handbrake	✓	Interior		75	Carpets	Average	
16	Dashboard Warning Lights	✓	47	Central Locking	✓ <th colspan="2">Keys and Locking</th> <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td>	Keys and Locking		76	Panels	Average	77	Dashboard	Average	
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>78</td> <td>Fuel Cap</td> <th>✓</th> <td>79</td> <td>Mud Flaps</td> <th>✓</th>	49	Number of Keys	1	78	Fuel Cap	✓	79	Mud Flaps	✓
18	Odometer	✓	Engine		50	Oil Level	✓ <td>80</td> <td>WOF</td> <th>✓</th> <td>81</td> <td>Wipers Front/Rear</td> <th>✓</th>	80	WOF	✓	81	Wipers Front/Rear	✓	
19	Rev Counter	•	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>82</td><td>Window Opener FL</td><th>✓</th><td>83</td><td>Window Opener FR</td><th>✓</th></th>	52	Performance	✓ <td>82</td> <td>Window Opener FL</td> <th>✓</th> <td>83</td> <td>Window Opener FR</td> <th>✓</th>	82	Window Opener FL	✓	83	Window Opener FR	✓
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>84</td><td>Window Opener RL</td><th>✓</th><td>85</td><td>Window Opener RR</td><th>✓</th></th>	54	Starter Motor	✓ <td>84</td> <td>Window Opener RL</td> <th>✓</th> <td>85</td> <td>Window Opener RR</td> <th>✓</th>	84	Window Opener RL	✓	85	Window Opener RR	✓
21	Wipers Front/Rear	✓							86	Rear View Mirrors	✓	87	Radio (Basic Test Only)	✓
22	Window Opener FL	✓							88	CD (Basic Test Only)	✓	89	Boot Open Switch	✓
23	Window Opener FR	✓							90			91		
24	Window Opener RL	✓							92			93		
25	Window Opener RR	✓							94			95		
26	Rear View Mirrors	✓							96			97		
27	Radio (Basic Test Only)	✓							98			99		
28	CD (Basic Test Only)	✓							100					
29	Boot Open Switch	✓												

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	09 Sep 2019
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--