

Report ID: 19,491,401 Version: 3 02 Jul 2019 Created:

Make:	Hyundai	Model:	130	Body Style:	Wagon	1		Pass	Fail	N/A	
Year:	2009	Registration: FTS996 Reg Expiry: 01 Oct 2019				Engine					
WoF Expiry:	11 Jul 2020	Odometer:	118,734 Kms	Good No:	19491401	Oi	il level	~			
VIN:	KMHDC81ER9U03756	Next Service:	130000	Service Histor	<b>y:</b> No	Sr	noke & fumes	~			
						Pe	erformance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						N	oise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coc	Cooling System				
a run mechanical inspection prior to purchase and this can be arranged for an additional charge.							polant condition	~			
	S		S* S		S	Pe	erformance	~			
ney.						Ra	adiator / Hoses (visual)	~			
S = scratch D = dent						Tra	nsmission			1	
B = rust SC D B S							peration	~			
PT = paint defect							oise	~			
C = crack							utch			~	
P = pin dent							/ joints	~			
							heel bearings	~			
SC = stone chips W = significant scuffs						Brakes					
W = significant scurs S S S S* SW SW						Pe	erformance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Ha	and Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)					
						Left front 2.5				mm	
						Ri	ght front	2	.5	mm	
						Le	eft rear	4	.5	mm	
Conditions During Body Inspection: Dry						Ri	Right rear 5.5			mm	
						Spare Yes					
Under Carriage & Under Bonnet Inspection Comments						Sus	pension				
2WD FL mud flap broken						Su	spension performance	~			
FL mud nap broken						St	eering performance	~			
							nock absorbers	~			
						Air Conditioning / Heater					
						Operation 🖌					
Interior Comments						Electrical / Accessories					
Seats	Good					He	ead lights	~			
Carnete	Good					Та	il lights	~			
Carpets						In	dicators	~			
Panels	Good					Da	ashboard warning lights	~			
Dashboa	Average			W	ipers (front & rear)	~					
						W	indow winder FL	~			
						i L w	indow winder FR	~			
<u>General Comments</u>						W	indow winder RL	~			
						W	indow winder RR	~			
							ear view mirrors	~			
							adio (basic test only)	~			
							D (basic test only)	~			
							umber of keys	1			
Road Con	ditions During Tes	t Drive:	Dry				entral locking	~			
	ming Machanian	Camala d					emote locking	~			
Engine Timing Mechanism: Cambelt							at. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Yes Kms: 112,000 Reversing camera										~	
Inspected by: Sudhin Ramachandran Date: 28 Jun 2019											
Inspected by: Sudhin Kamachandrah Date: 28 Jun 2019											

I have read and understood this condition guide.

Name: .....

Signature: .....