

Basic Vehicle Condition Guide

Report ID: 19,492,476

Pass

Version:

Engine

Oil level

Smoke & fumes

Created: 17 May 2019


Fail

N/A

Make: Model: Holden Colorado **Body Style:** Utility Year: 2014 Registration: HGJ131 Reg Expiry: 11 Oct 2019 WoF Expiry: **Odometer:** 23 Apr 2020 257,844 Kms **Good No:** 19492476 VIN: MMU148DK0EH60629 **Next Service:** 261,850kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Detachable tow bar.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Inspected by:

Good 4x4 d/cab ute. On road noise, possibly tyres.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

| Performance | ~ | | | |
|------------------------------|-----------------|---------|-----|--|
| Noise | ~ | | | |
| Cooling System | | | • | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | • | |
| Operation | ~ | | | |
| Noise | \(\times \) | | | |
| Clutch | ~ | | | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | • | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 1 | 2 | mm | |
| Right front | 1 | 3 | mm | |
| Left rear | 12 | | mm | |
| Right rear | 11 mm | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | \(\triangle \) | | | |
| Window winder FR | ~ | | | |
| Window winder RL | V | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 1 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | 1 | |

Daryll Timms I have read and understood this condition guide.

Name:

Signature:

17 May 2019