

Report ID: 19,495,133 Version: 3 25 Oct 2019 Created:

Make:	Holden	Model:	Viva	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:	HHQ476	Reg Expiry:	01 Oct 2019	Engine			L
WoF Expiry:		Odometer:	165,782 Kms	Good No:	19495133	Oil level	~		
VIN:	KL3NF48BJ6K302330	Next Service:		Service Histor		Smoke & fumes	~		
					,. no	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			1
		_				Performance	~		
Key:	SC	-0	S SC S SC		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent									
R = rust PT = paint defect C = crack						Operation	~		
						Noise Clutch	~		
P = pin dent									~
* = decals S D SC P P						CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S SC S						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<u> </u>	
Minor stone chips in the windscreen ,						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front	7.0 mm		-
						Right front		.0	mm
						Left rear	7	.0	mm
Conditions During Body Inspection: Dry						Right rear	7	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
						Operation	~		
Interior Comments						Electrical / Accessories		1	
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
	-				 	Window winder FR	~		
General Comments						Window winder RL	~		
Stereo not	working needs a code,A	ir bag light is on	,			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 61	,514	Reversing camera			~
Inspected by: Donovan Matara Date: 12 Jun 2019									
I have read and understood this condition guide. Name:									