

Basic Vehicle Condition Guide

Report ID: 19,496,083


Version: 1

Created: 23 May 2019

Make: Model: Mercedes-Benz **GL-Class Body Style:** SUV Year: 2011 Registration: LZH304 Reg Expiry: 27 Jun 2019 WoF Expiry: **Odometer:** 27 Apr 2019 181,508 Kms **Good No:** 19496083 VIN: WDC1648222A655747 **Next Service:** 186,271kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

No jack or tools.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Tidy.

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Good | | |
| Carpets | Average | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Rear windows only working from master switch.

CD player not taking disc.

Tidy 7 seater 4WD SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

Daryll Timms Date: 23 May 2019 Inspected by:

| | Pass | Fail | N/A | | |
|------------------------------|---|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | VVV | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | <i>V</i> | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ' | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | | 5 | mm | | |
| Right front | | 5 | mm | | |
| Left rear | : | 3 | mm | | |
| Right rear | 3 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | 1 | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | \(\times \) | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | VVV | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | ~ | | | |
| Number of keys | 2 | I | I | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | · | | | | |
| Reversing camera | ~ | | | | |
| <u> </u> | | | | | |

I have read and understood this condition guide.

Name:

Signature: