

Report ID: 19,496,201 Version: 2 23 May 2019 Created:

Make:	Nissan	Model:	Maxima	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	DPJ926	Reg Expiry:	28 Sep 2019	Engine			
WoF Expiry:		Odometer:	146,312 Kms	Good No:	19496201	Oil level	~		
VIN:	JN1BBUJ31A0050337	Next Service:		Service Histor		Smoke & fumes	~		
					,	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:		0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				100	BID	Operation			
R = rust				10		Noise	<b>v</b>		
PT = paint defe C = crack	ect 1			+	SC SC	Clutch	~		
P = pin dent	LHC								~
* = decals	sc pp			SI	ANA	CV joints	~		
SC = stone chi	ps V	LA		10	\$P	Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		<u> </u>	Ļ
Stone chips front screen. Screw holes in dash					Tyres (lowest observed tread depth of tyres)				
						Left front	5.0		mm
						Right front	4.0	)	mm
						Left rear	6.0	)	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes			
<u>Under Ca</u>	image & Under Bor	inet inspectic	on comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Poor					Wipers (front & rear)	~		
	iiu					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central lo							~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test or									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 21 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....