

Report ID: 19,497,782 Version: 5 Created: 12 Oct 2019

Make:	Holden	Model:	Captiva 5	Body Style:	SUV		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	EQW900	Reg Expiry:	18 Sep 2019	Engine	1		L
WoF Expiry:	13 Aug 2020	Odometer:	128,783 Kms	Good No:	19497782	Oil level	~		
VIN:	KL3CD26RJ9B266939	Next Service:	134345	Service Histor	y: No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S		S P S SC		S	Performance	V		
Key:	L'	-0	3P 33C			Radiator / Hoses (visual)	~		
S = scratch						Transmission			I
D = dent R = rust S SC S SC S SC						Operation	~		
PT = paint defect						Noise	V		
C = crack						Clutch			~
P = pin dent	HIG				74114	CV joints	V		
* = decals	sc 816			-July	ELD'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S S P D						Performance			
Redulars and the diagram Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			L es)
						Left front 7.0			
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear		.0	mm
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD						Suspension performance	~		
Engine oil s	ump damage					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation			
Interior Comments						Electrical / Accessories	•		L
Seats	Seats Good					Head lights	~		
	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average				Dashboard warning lights	~			
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
<u>General</u> (	<u>Comments</u>					Window winder RL	~		$\left  - \right $
Orange warning lights on for Traction Control and ABS.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Dead Canditions During Test Driver D						Central locking	· ·		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
									_ <b>*</b>
Inspected by: Bobby Zhong Date: 22 Aug 2019									
I have read and understood this condition guide. Name:									