

Report ID: 19,497,912 Version: 4 Created: 15 Jul 2019

Make:	Hyundai	Model:	Terracan	Body Style:	SUV		Pass	Fail	N/A
Year:	2004	Registration:	CKE66	Reg Expiry:	01 Sep 2019	Engine	1		
WoF Expiry:		Odometer:	227,278 Kms	Good No:	19497912	Oil level	~		
VIN:	KMHNM81XR5U16461	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta hava aat		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	P	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN	S D	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack				+		Clutch			~
P = pin dent					741L	CV joints	~		
* = decals	sc 916			-Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	mav not be disc	blaved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyr			es)
						Left front 6.0			
						Right front		.0	mm
						Left rear		.0	mm
Condition	as During Padulas	aaction	Dura			Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil s	-	·				Suspension performance	~		
transmissio	n oil leaks					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior C	omments					Electrical / Accessories	•		
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
AWD						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	I	<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	-		~
L						-	1	1	
Inspecte	d by: Bobby Zhong					Date: 12 Jul 201	9		

I have read and understood this condition guide.

Name:

Signature: