

Report ID: 19,497,931 Version: 2 27 May 2019 Created:

Make:	BMW	Model:	Z4	Body Style:	Convertible		Pass	Fail	N/A	
Year:	2004	Registration:		Reg Expiry:	30 Aug 2019	Engine		-		
WoF Expiry:	24 May 2020	Odometer:	126,500 Kms	Good No:	19497931	Oil level	~			
VIN:	WBABT12080LR01793	Next Service:		Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		с I II	.		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	SD	-0	SC			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	sw 6/6			The		Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint defe C = crack				+		Clutch			~	
P = pin dent						CV joints	~			
* = decals	s pip				ENR	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs PT W						Performance	~		<u> </u>	
			dofocts & blomishor		laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	- f t wa		
Both sills paint defect						Tyres (lowest observed tread depth of tyres)				
						Left front	5.	-	mm	
						Right front	5.		mm	
						Left rear	3.		mm	
Conditions During Body Inspection: Dry						Right rear	510		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare	N/A			
		meenspeede	<u>in comments</u>			Suspension			<u> </u>	
						Suspension performance	~		<u> </u>	
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Average						lectrical / Accessories				
Seats	Avelage					Head lights	~		<u> </u>	
Carpets	Average					Tail lights	~			
	A					Indicators	~		<u> </u>	
Panels	Average					Dashboard warning lights	~		<u> </u>	
Dashboa	Average					Wipers (front & rear)	~			
						Window winder FL	~		<u> </u>	
						Window winder FR	~			
<u>General Comments</u>						Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
		· · ·	·			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Greg Morgan Date: 27 May 2019									

I have read and understood this condition guide.

Name:

Signature: