

Basic Vehicle Condition Guide

Report ID: 19,499,064


Version: 3

18 Jun 2019 Created:

Make: Model: Ford Kuga **Body Style:** SUV Year: 2015 Registration: MCT140 Reg Expiry: 28 Jun 2019 WoF Expiry: **Odometer:** 26 Jun 2020 94,991 Kms **Good No:** 19499064 VIN: WF0AXXWPMAFE897{ Next Service: 100270 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on the windscreen RL tyre side wall cut (minor) FR door seal worn

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4WD

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Bobby Zhong

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>V</i>		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5.5		mm
Right front	5.5		mm
Left rear	4.5		mm
Right rear	5.5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Domata lacking			
Remote locking	~		

I have read and	understood	this cond	ition guide.

18 Jun 2019

Reversing camera