

Report ID: 19,499,644 Version: 4 08 Aug 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:	12 Jan 2020	Engine	1		1
WoF Expiry:		Odometer:	60,691 Kms	Good No:	19499644	Oil level	~		<u> </u>
VIN:	6G1PD6E50CL617018	Next Service:	73,319	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechar	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s AR			20		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				2416	CV joints	~		
* = decals		10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S		S S			Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
<u></u>						Tyres (lowest observed tread depth of tyres)			
						Left front	177	3	mm
						Right front	3	3	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear 4 m			mm
		Spare Yes							
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
General	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		T
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Mathew Varghese Date: 08 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: