

Basic Vehicle Condition Guide

Report ID: 19,499,692


Version: 3

Created: 23 Jun 2019

Make: Model: Toyota Landcruiser Prado **Body Style:** SUV Year: 2013 Registration: GYC734 Reg Expiry: 23 Jun 2019 **Odometer:** WoF Expiry: 24 Jun 2020 193,088 Kms **Good No:** 19499692 VIN: JTEBH3FJ30K107563 Next Service: 195,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Wet

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

AWD

Interior Comments			
Seats	Average		
Carpets	Good		
Panels	Average		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Bobby Zhong

s Kms: 150,000

	Pass	Fail	N/A
Engine			•
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	7.0		mm
Right front	7.0		mm
Left rear	7.0 mm		mm
Right rear	7.0		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \) \(\t		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	V		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			1

I have read and understood this condition guide.

Name:

Signature:

20 Jun 2019

Reversing camera