


<b>Make:</b> Ford	<b>Model:</b> Transit	<b>Body Style:</b> Van
<b>Year:</b> 2012	<b>Registration:</b> GJM132	<b>Reg Expiry:</b> 27 Aug 2019
<b>WoF Expiry:</b> 22 May 2020	<b>Odometer:</b> 232,190 Kms	<b>Good No:</b> 19501084
<b>VIN:</b> WF0XXXTFXC5399C	<b>Next Service:</b> 250,000kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs


**Body Inspection Comments**

Note: some defects &amp; blemishes may not be displayed in the diagram

- Adjustment handles on side of drivers seat are missing.
- Stone chips in windscreen.
- Number plate light cover is missing.
- Plastic Trim under petrol flap is missing.
- Plastic centre cap is missing off left front & right rear wheels.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

- Front brake disc/rotors worn.

**Interior Comments**

Seats	Good
Carpets	Average
Panels	Average
Dashboard	Good

**General Comments**

- Engine light staying on.
- Engine is lacking power.
- Engine oil level on low mark on engine dip stick.
- Trim panel buttons are missing on side of right side sliding door.
- Trim cover missing off inside sliding door handle.
- Hole in rubber floor mat in right front.
- Badge on front grille is coming unstuck, badge off tailgate is missing.

Road Conditions During Test Drive: Dry

 Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Performance		✓	
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	9.0	mm	
Right front	9.0	mm	
Left rear	9.0	mm	
Right rear	9.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 05 Jun 2019

I have read and understood this condition guide. Name: ..... Signature: .....