

Report ID: 19,501,084 Version: 4 14 Aug 2019 Created:

Make:	Ford	Model:	Transit	Body Style:	Van		Pass	Fail	N/A
Year:	2012	Registration:	GJM132	Reg Expiry:	28 Aug 2019	Engine	1		1
WoF Expiry:	22 May 2020	Odometer:	232,216 Kms	Good No:	19501084	Oil level	~		<u> </u>
VIN:	WF0XXXTTFXCB53990	Next Service:	250,000kms	Service Histor	y: No	Smoke & fumes	~		-
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		+
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			1
						Performance	~		+
Key:	SPSC	-0	S S	-161-	SR	Radiator / Hoses (visual)	~		+
S = scratch						Transmission			<u> </u>
D = dent						Operation	~		T
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack					S SC	Clutch	~		
P = pin dent						CV joints	•		~
* = decals S R P SC P P						Wheel bearings	~		-
SC = stone chips						Brakes	V		L
W = significant scuffs SDSC S SP SP SDR						Performance V			Τ
Note: come defecte % blamiches may not be dienlayed in the diagram						Hand Brake	~		+
Body Inspection Comments							•	ofter	
- Adjustment handles on side of drivers seat are missing. - Stone chips in windscreen.						Left front	Tyres (lowest observed tread depth of tyres)		
- Stone chips in windscreen. - Number plate light cover is missing.							9		mm
- Plastic Trim under petrol flap is missing.						Right front	9		mm
- Plastic centre cap is missing off left front & right rear wheels.						Left rear	9		mm
Conditions During Body Inspection: Dry						Right rear	9 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	inet inspectic	<u>In comments</u>			Suspension			·
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments Average						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
	-				 	Window winder FR	~		
General Comments						Window winder RL			~
- Trim panel buttons are missing on side of right side sliding door. - Trim cover missing off inside sliding door handle.						Window winder RR			~
- Hole in ru	ober floor mat in right fi	ront.				Rear view mirrors	~		
- Badge on	front grille is coming ur	istuck, badge off	tailgate is missing.			Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	_		•			Remote locking		~	1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							I		<u> </u>
Inspecte	d by: Stuart Melbourr	Date: 14 Aug 20	19						
I have read and understood this condition guide. Name:									