



Turners Certified Imports 50 Point Check

Report ID: 19,501,182
Version: 1
Created: 28 May 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Honda Body Style:
Model: Airwave Odometer: 96,471 Kms
Year: 2008 VIN: 7AT08GBNX19210262

Under Carriage & Under Bonnet Inspection Comments

General Comments

Front wheel drive

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable
Replaced At (odometer reading):
Road Conditions During Test Drive: Wet

Electrical

Battery	☒
Head lights	☒
Tail lights	☒
Indicators	☒
Dashboard warning lights	☒
Wipers (front & rear)	☒
Window winder FL	☒
Window winder FR	☒
Window winder RL	☒
Window winder RR	☒
Rear view mirrors	☒
Radio (basic test only)	☒
CD (basic test only)	☒
Reversing camera	☒

Transmission & Drive

Operation	☒
Noise	☒
Clutch	☐
CV joints	☒
Wheel bearings	☒
Wheel balance	☒

Brakes

Performance	☒
Hand Brake	☒

Keys & Locking

Central locking	☒
Remote locking	☐
Number of keys	1

Engine

Oil level	☒
Smoke & fumes	☒
Performance	☒
Noise	☒

Cooling System

Coolant condition	☒
Performance	☒
Radiator / Hoses (visual)	☒

Suspension

Suspension performance	☒
Steering performance	☒
Shock absorbers	☒

Tyres (lowest observed tread depth)

Left front	4 mm
Right front	4 mm
Left rear	3.5 mm
Right rear	3.5 mm
Spare	Yes
Tools	☒

Interior

AC Operation	☒
Heater fan	☒
Seatbelts	☒
Horn	☒

Turners Certified Key

✓ = Pass X = Fail
• = Not applicable for this vehicle

Inspected by: Xinghui Lin

Date: 28 May 2019

I have read and understood this condition guide.

Name:

Signature: