

Report ID: 19,502,221 Version: 2 04 Jun 2019 Created:

| Make: | Mitsubishi | Model: | Outlander | Body Style: | SUV | | Pass | Fail | N/A |
|--|---------------------------|-----------------|------------------------|---------------------------------|----------------------|--|------|------|-----|
| Year: | 2007 | Registration: | MDR846 | Reg Expiry: | 10 Dec 2019 | Engine | | | |
| WoF Expiry: | 26 Jun 2019 | Odometer: | 67,640 Kms | Good No: | 19502221 | Oil level | ~ | | |
| VIN: | 7AT0CJ3MX18107047 | Next Service: | 75,000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | r | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | r | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | lical inspection prior to | purchase and th | his can be arranged fo | or an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| D = dent R = rust | | | | 715 | HIV | Operation | ~ | | |
| PT = paint defe | ect NP | r I | | $\left[\left(\right) \right]$ | 7014 | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HID | | | | 74116 | CV joints | ~ | | |
| * = decals | - Alt | | | Too . | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| w – signincan | | | | | S | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | Left front | 8 | 3 | mm | |
| | | | | | | Right front | 8 | 3 | mm |
| | | | | | | Left rear | 8 | 3 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 8 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| 4WD | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpote | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| Enging Ti | ming Mechanism: | Timina | ⁻ hain | | | Remote locking | ~ | | |
| - | - | Timing (| | Vrag | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspected by: Mathew Varghese Date: 04 Jun 2019 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: