



# Turners Certified Imports 50 Point Check

Report ID: 19,502,746  
Version: 1  
Created: 30 May 2019

**Note: This report is not a warranty**  
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

|                |                        |
|----------------|------------------------|
| Make: Nissan   | Body Style: SUV        |
| Model: Elgrand | Odometer: 128,602 Kms  |
| Year: 2013     | VIN: 7AT0DH6MX19052638 |

Under Carriage & Under Bonnet Inspection Comments  
Front wheel drive

General Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

|                                    |                |
|------------------------------------|----------------|
| Engine Timing Mechanism:           | Timing Chain   |
| Evidence of Cam Belt Replacement:  | Not Applicable |
| Replaced At (odometer reading):    |                |
| Road Conditions During Test Drive: | Dry            |

| Electrical               |                                     |
|--------------------------|-------------------------------------|
| Battery                  | <input checked="" type="checkbox"/> |
| Head lights              | <input checked="" type="checkbox"/> |
| Tail lights              | <input checked="" type="checkbox"/> |
| Indicators               | <input checked="" type="checkbox"/> |
| Dashboard warning lights | <input checked="" type="checkbox"/> |
| Wipers (front & rear)    | <input checked="" type="checkbox"/> |
| Window winder FL         | <input checked="" type="checkbox"/> |
| Window winder FR         | <input checked="" type="checkbox"/> |
| Window winder RL         | <input checked="" type="checkbox"/> |
| Window winder RR         | <input checked="" type="checkbox"/> |
| Rear view mirrors        | <input checked="" type="checkbox"/> |
| Radio (basic test only)  | <input checked="" type="checkbox"/> |
| CD (basic test only)     | <input checked="" type="checkbox"/> |
| Reversing camera         | <input checked="" type="checkbox"/> |

| Transmission & Drive |                                     |
|----------------------|-------------------------------------|
| Operation            | <input checked="" type="checkbox"/> |
| Noise                | <input checked="" type="checkbox"/> |
| Clutch               | <input type="checkbox"/>            |
| CV joints            | <input checked="" type="checkbox"/> |
| Wheel bearings       | <input checked="" type="checkbox"/> |
| Wheel balance        | <input checked="" type="checkbox"/> |
| Brakes               |                                     |
| Performance          | <input checked="" type="checkbox"/> |
| Hand Brake           | <input checked="" type="checkbox"/> |
| Keys & Locking       |                                     |
| Central locking      | <input checked="" type="checkbox"/> |
| Remote locking       | <input checked="" type="checkbox"/> |
| Number of keys       | <input type="text" value="1"/>      |

| Engine                    |                                     |
|---------------------------|-------------------------------------|
| Oil level                 | <input checked="" type="checkbox"/> |
| Smoke & fumes             | <input checked="" type="checkbox"/> |
| Performance               | <input checked="" type="checkbox"/> |
| Noise                     | <input checked="" type="checkbox"/> |
| Cooling System            |                                     |
| Coolant condition         | <input checked="" type="checkbox"/> |
| Performance               | <input checked="" type="checkbox"/> |
| Radiator / Hoses (visual) | <input checked="" type="checkbox"/> |
| Suspension                |                                     |
| Suspension performance    | <input checked="" type="checkbox"/> |
| Steering performance      | <input checked="" type="checkbox"/> |
| Shock absorbers           | <input checked="" type="checkbox"/> |

| Tyres (lowest observed tread depth) |                                     |
|-------------------------------------|-------------------------------------|
| Left front                          | <input type="text" value="5.0"/> mm |
| Right front                         | <input type="text" value="5.0"/> mm |
| Left rear                           | <input type="text" value="6.0"/> mm |
| Right rear                          | <input type="text" value="6.0"/> mm |
| Spare                               | <input type="text" value="Yes"/>    |
| Tools                               | <input checked="" type="checkbox"/> |

| Interior     |                                     |
|--------------|-------------------------------------|
| AC Operation | <input checked="" type="checkbox"/> |
| Heater fan   | <input checked="" type="checkbox"/> |
| Seatbelts    | <input checked="" type="checkbox"/> |
| Horn         | <input checked="" type="checkbox"/> |

**Turners Certified Key**  
 = Pass       = Fail  
 = Not applicable for this vehicle

Inspected by: Ca Thach      Date: 29 May 2019

I have read and understood this condition guide.      Name: .....      Signature: .....