

Report ID: 19,502,812 Version: 1 07 Jun 2019 Created:

Make:	Mitsubishi	Model:	380	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:	DTH686	Reg Expiry:	31 Mar 2020	Engine	I		L
WoF Expiry:	04 Apr 2020	Odometer:	127,766 Kms	Good No:	19502812	Oil level	~		
VIN:	6MMDB4D416T01044	Next Service:	128631	Service Histor	<b>y:</b> No	Smoke & fumes	~		<u> </u>
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or					Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SD	-0	S P SC S P SC	-01-	S SC	Radiator / Hoses (visual)	~		<u> </u>
S = scratch						Transmission	sion		
D = dent	SD 615			TIN	FIL S	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent					세비	CV joints	~		-
* = decals	ssc 916			- AL	ETTP IS	Wheel bearings	~		
SC = stone chips						Brakes	v		
W = significant scuffs SC SC S SC S P SC						Performance	~		
		Note: son		may not be disc		Hand Brake	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
						Tyres (lowest observed tread depth of ty Left front 5			mm
								<b>.</b>	
						Right front Left rear	5		mm
								7	mm
Conditions During Body Inspection: Wet						Right rear	7	7	mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	-	<u>ince inspectic</u>	<u>on comments</u>			Suspension			1
Minor oil le	dK,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	//veruge					Head lights	~		-
Carpets	Average					Tail lights	~		
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
Dashbud						Window winder FL	~		<u> </u>
<u> </u>						Window winder FR	~		
<u>General Comments</u> Slight ticking noise coming from motor ,check engine light is on ,					Window winder RL	~			
Slight tickir	ig noise coming from m	lotor ,check engi	ne light is on ,			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
	-	- ·				Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 10	02,395	Reversing camera			~
have stadily. Denover Materia									
Inspected by: Donovan Matara Date: 07 Jun 2019									
I have read	and understood th	is condition o	juide. Name: .			Signature:			