

Basic Vehicle Condition Guide

Report ID: 56,657

Version: 4

Engine

Oil level

Smoke & fumes

21 Jun 2019 Created:

Pass

1


N/A

Fail

Make: Toyota Model: Highlander **Body Style:** SUV Year: 2004 Registration: CFT493 **Reg Expiry:** 10 Dec 2019 **WoF Expiry: Odometer:** 19 Jun 2020 193,516 Kms **Good No:** 19503302 VIN: JTEHP21A700043389 **Next Service:** 203528 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Shocks soft

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General	Comments

Oil leak

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 89,000

Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 5.0 Right front 5.0 mm Left rear 4.0 mm Right rear 4.0 mm Spare Yes Suspension Suspension performance 1 Steering performance Shock absorbers ~ Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) 1

Reversing camera

1

Signature:

29 May 2019 Inspected by: Scott Date:

Name: