

Report ID: 19,503,961 Version: 1 17 Jun 2019 Created:

Make:	Toyota	Model:	Aurion	Body Style:	Sedan		Pass	Fail	N/A
Year:	2007	Registration:	EBD599	Reg Expiry:	10 Dec 2019	Engine			
WoF Expiry:	12 Mar 2020	Odometer:	252,530 Kms	Good No:	19503961	Oil level	~		
VIN:	6T153KK400X285297	Next Service:	262523	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	or an additional of	charge.	Coolant condition	~		
						Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				2414	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
- Significan						Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
"						Tyres (lowest observed tread depth of tyres)			
					Left front	5	.0	mm	
						Right front	5	.0	mm
						Left rear	:	3	mm
Conditions During Body Inspection: Wet						Right rear	3 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine oil le	eaks					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
	· · · · · · · · · · · ·					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet							~		
Enging Ti	ning Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~
	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris Vanner Date: 28 May 2019									

I have read and understood this condition guide.

Name:

Signature: