

Report ID: 19,504,277 Version: 2 08 Jul 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A	
Year:	2015	Registration:	JFG704	Reg Expiry:	14 Jul 2019	Engine	1 435			
WoF Expiry:		Odometer:	70,976 Kms	Good No:	14 Jul 2019 19504277	Oil level	~			
VIN:	MMU148EK0FH62795			Service Histor		Smoke & fumes	~		 	
			, , ,000KIII3		. 103	Performance	~		 	
	port is not a warranty					Noise	~		 	
	a guide only. Conside sting undertaken. The					Cooling System	•		L	
a full mechan	ical inspection prior to	purchase and th	his can be arranged f	or an additional of	charge.	Coolant condition	~			
		_				Performance	~		─	
Key:	S SC	-0	S S		s	Radiator / Hoses (visual)	~			
S = scratch	50	20		10/2	X	Transmission	V			
D = dent	ssc dl				BID		~		1	
R = rust				10		Operation Noise	~			
PT = paint defects a construction of the second s	ect			+	SC		~		<u> </u>	
C = crack P = pin dent	LHO					Clutch			v	
* = decals	s sc db					CV joints			~	
SC = stone chips						Wheel bearings	~			
W = significant scuffs S						Brakes				
						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		(·	Ļ	
Front tyres edges worn						Tyres (lowest observed tread depth of tyres)				
1 remote key worn						Left front	2 mm			
						Right front	3		mm	
						Left rear	2		mm	
Conditions During Body Inspection: Wet					Right rear	5	5	mm		
Linder Carriege & Linder Demot la constitue Community						Spare		Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Rear wheel	drive					Suspension performance	~		<u> </u>	
						Steering performance	~		<u> </u>	
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation	~			
Interior Comments						Electrical / Accessories	,			
Seats	Good					Head lights	~		<u> </u>	
Carpets	Floor mats	missing				Tail lights	~		<u> </u>	
						Indicators	~			
Panels	Average					Dashboard warning lights	~		<u> </u>	
Dashboa	Good					Wipers (front & rear)	~			
Dastibud						Window winder FL	~			
	_					Window winder FR	~			
General (<u>Comments</u>					Window winder RL	<			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Con	ditions During Test	t Drive:	Wet			Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~	
Inspected by: Bobby Zhong						Date: 08 Jul 201	9			
I have read	and understood th	is condition o	juide. Name:			Signature:				