

Report ID: 19,504,594 Version: 2 Created: 02 Jul 2019

Make:	Honda	Model:	Stream	Body Style:	SUV		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	LKR526	<b>Reg Expiry:</b>	31 Aug 2019	Engine			1
WoF Expiry:	20 Jul 2019	Odometer:	120,058 Kms	Good No:	19504594	Oil level	~		
VIN:	7AT08GADX18020637	Next Service:	n.a	Service Histor	<b>y:</b> No	Smoke & fumes	~		
_						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC		Р			Performance	V		
Key:	ISC (	-0				Radiator / Hoses (visual)	V		
S = scratch						Transmission			L
D = dent	SC DI			215	SW.	Operation	~		
R = rust PT = paint def				$\left[ \right] \left[ \right]$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					세비	CV joints	~		-
* = decals	sc 916			- AL	EIIP I	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC S W SC D						Performance			
		Note: son	ne defects & blemishe	 s may not be disr	laved in the diagram	Hand Brake	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	
						Left front			
						Right front		.2	mm
						Left rear		.2	mm
								0.0	
Conditions During Body Inspection: Dry						Right rear	6	6.2 mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	meenspeede	<u>on comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats	/weitige					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		
curpets	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
Dastibud						Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
- Seatbelt badly damaged on left rear seat (boot seat. WOF fail). - Jack missing.						Window winder RR	~		
- Service sti	cker shows no record of	f when service is	due.			Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		_
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
			•			Remote locking	~		
•	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Anna-Lise Ferguson Date:							19		
I have read	and understood th	is condition g	juide. Name:			Signature:			