



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,504,745
Version:	2
Created:	06 Sep 2019

Make:	Suzuki	Body Style:	Hatchback
Model:	Splash	VIN:	TSMEXB32S00510074
Year:	2011	Odometer:	51,707 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>36</td> <td>Clutch</td> <td>•</td> <td>60</td> <td>Shock Absorbers</td> <th>✓</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	36	Clutch	•	60	Shock Absorbers	✓	85	R/H Mirror	Good			
6	Front Left Indicators	✓	37	CV Joints	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>6</td> <td>mm</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	Wheels and Tyres		61	Left Front	6	mm	86	L/H Mirror	Good			
7	Rear Right Indicators	✓	38	Wheel Bearing	✓ <td>62</td> <td>Right Front</td> <td>6</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	6	mm	63	Left Rear	7	mm	87	L/F Guard	Good	
8	Rear Left Indicators	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>6</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	64	Right Rear	6	mm	65	Spare	Yes	88	R/F Guard	Good		
9	Reversing Lights	✓	40	Gearbox (Manual)	•	66	Tools	✓	67	AC Operation	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good			
10	Rear Reflectors	•	41	Engine Timing	Timing Chain	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>	90	R/H Doors	Good			
11	Hazard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>91</td> <td>L/H Sill</td> <td>Good</td>	71	Seat Heaters	•	91	L/H Sill	Good			
12	Courtesy Lights	•	43	Replaced at (odometer reading)		72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good			
13	Dashboard Lights	✓	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>front seats marked</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	74	Seats	front seats marked	75	Carpets	Good	93	Boot/Tail Gate	Good	
14	Dashboard Dimmer Switch	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td>77</td><td>Dashboard</td><td>Good</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	46	Handbrake	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	76	Panels	Good	77	Dashboard	Good	94	Front Bumper	Good
15	Number Plate Light	✓	Keys and Locking		47	Central Locking	✓ <td>78</td> <td>Fuel Cap</td> <th>✓<td>79</td><td>Mud Flaps</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	78	Fuel Cap	✓ <td>79</td> <td>Mud Flaps</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	79	Mud Flaps	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good	
16	Dashboard Warning Lights	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>80</td> <td>WOF</td> <th>✓<td>96</td><td>Roof</td><td>Good</td><td>97</td><td>Bonnet</td><td>Good</td></th>	49	Number of Keys	1	80	WOF	✓ <td>96</td> <td>Roof</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	96	Roof	Good	97	Bonnet	Good
17	Speedo	✓	Engine		50	Oil Level	✓ <td>81</td> <td>Front Windscreen (no chips)</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>	81	Front Windscreen (no chips)	Good	98	Fuel Cap	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓	
18	Odometer	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td><td>99</td><td>Mud Flaps</td><th>✓<td>100</td><td>WOF</td><th>✓</th></th></th>	52	Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	82	Side Windows (no chips)	Good	99	Mud Flaps	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓
19	Rev Counter	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td><td></td><td></td><td></td><td></td><td></td><td></td></th>	54	Starter Motor	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	83	Front Wiper Blades	Good						
20	Fuel Gauge	✓							84	Rear Wiper Blade	Good						
21	Wipers Front/Rear	✓							85	R/H Mirror	Good						
22	Window Opener FL	✓							86	L/H Mirror	Good						
23	Window Opener FR	✓							87	L/F Guard	Good						
24	Window Opener RL	✓							88	R/F Guard	Good						
25	Window Opener RR	✓							89	L/H Doors	Good						
26	Rear View Mirrors	✓							90	R/H Doors	Good						
27	Radio (Basic Test Only)	✓							91	L/H Sill	Good						
28	CD (Basic Test Only)	✓							92	R/H Sill	Good						
29	Boot Open Switch	✓							93	Boot/Tail Gate	Good						

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Kelly	Date:	06 Sep 2019
---------------	------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--