

Report ID: 19,506,642 Version: 3 18 Jun 2019 Created:

Make:	Hyundai	Model:	Imax	Body Style:	People Mover		Pass	Fail	N/A
Year:	2016 Registration: KBC899 Reg Expiry: 30 May 2019					Engine			
WoF Expiry:	28 Jun 2020	Odometer:	82,582 Kms	Good No:	19506642	Oil level	~		
VIN:	KMHWH81RMGU8527	Next Service:		Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
				·		Performance	~		
	port is not a warranty	aration is made	for age and miloage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	S SSC		sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S SC S SC S SC						Operation	~		
R = rust PT = paint defe				$\prod$		Noise	~		
C = crack						Clutch			~
P = pin dent					세비	CV joints			~
* = decals	sc 916			The	ELL SC	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs S S W S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
	pection Comments					Tyres (lowest observed trea	•	of tyre	
Floor mats missing						Left front 7.5 mm			
						Right front	7.		 mm
						Left rear	7.		mm
Canditiana Duvina Dadukana atian. D						Right rear		-	mm
Conditions During Body Inspection: Dry						Spare	7.5		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
2WD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories			
Good						Head lights			
Seats									
Carpets	FR carpet	worn				Tail lights Indicators	~ ~		
De 12	Good						-		
Panels						Dashboard warning lights Wipers (front & rear)	~ ~		
Dashboa	Good					Window winder FL	-		
						Window winder FL Window winder FR	<b>v</b>		
General (	Comments					Window winder FR Window winder RL	~		
						Window winder RL Window winder RR			<b>v</b>
						Rear view mirrors			~
							<b>v</b>		
						Radio (basic test only)	~		
						CD (basic test only)	-		~
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
Enaine Tir	ming Mechanism:	Timing (	 [hain			Remote locking	~		
-	of Cam Belt Replac	-	lot Applicable	Kms:		Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: Bobby Zhong Date: 18 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....