

Basic Vehicle Condition Guide

Report ID: 19,507,451


Version: 3

Created: 18 Jul 2019

Make: Model: Mazda Mazda6 **Body Style:** Hatchback Year: 2010 Registration: **GFQ383** Reg Expiry: 22 Jul 2019 WoF Expiry: **Odometer: Good No:** 25 Jul 2020 188,972 Kms 19507451 VIN: JM0GH105100137647 **Next Service:** 195000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

2WD

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Bobby Zhong

Create	d: 18 	3 Jul 20	19
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\triangle \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission		I	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	(5	mm
Right front	5	.5	mm
Left rear	6	.5	mm
Right rear	6	6.5	
Spare		Yes	
Suspension		ı	
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories			ı
Head lights	~		
Tail lights	\(\times \)		
Indicators	~		
Dashboard warning lights			
Wipers (front & rear)	/		
Window winder FL	\(\triangle \)		
Window winder FR	<i>V</i>		
Window winder RL	•		
Window winder RR	V		
Rear view mirrors	•		
Radio (basic test only)	•		
CD (basic test only)	~		
Number of keys	2		
Central locking	•		
Remote locking	-		
Sat. Nav. (basic test only)			<i>'</i>
Reversing camera			'

П	have read	l and	unc	lerstood	l this	condition	guide	

Name	

18 Jul 2019

Date: