

Report ID: 19,507,480


Version: 1

Created: 18 Jun 2019

Make:	Hyundai	Model:	lload	Body Style:	Van
Year:	2014	Registration:	HHM899	Reg Expiry:	27 Aug 2019
WoF Expiry:	07 May 2020	Odometer:	114,760 Kms	Good No:	19507480
VIN:	KMFWBX7KMEU61546	Next Service:	120,000kms	Service Histor	y: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Both taillight cracks 1 remote key fail Left taillight fail

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive Oil around turbo

<u>Interior Comments</u>					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A				
Engine		-					
Oil level	~						
Smoke & fumes	~						
Performance	\(\times \)						
Noise	~						
Cooling System							
Coolant condition	~						
Performance	V						
Radiator / Hoses (visual)	~						
Transmission							
Operation	~						
Noise	~						
Clutch			~				
CV joints			~				
Wheel bearings	~						
Brakes							
Performance	~						
Hand Brake	~						
Tyres (lowest observed tread depth of tyres)							
Left front	3	.5	mm				
Right front	4		mm				
Left rear	4		mm				
Right rear	4		mm				
Spare	Yes						
Suspension							
Suspension performance	>						
Steering performance	V						
Shock absorbers	~						
Air Conditioning / Heater							
Operation	>						
Electrical / Accessories							
Head lights	'						
Tail lights		~					
Indicators	~						
Dashboard warning lights	~						
Wipers (front & rear)	~						
Window winder FL	~						
Window winder FR	~						
Window winder RL			~				
Window winder RR			~				
Rear view mirrors	~						
Radio (basic test only)	~						
CD (basic test only)	~						
Number of keys	2	1					
Central locking	~						
Remote locking	~						

Sat. Nav. (basic test only)

Signature:

Reversing camera

1

18 Jun 2019 Inspected by: Ca Thach Date:

Name: