

## **Basic Vehicle Condition Guide**

Report ID: 19,507,700


Version: 2

Created: 11 Jul 2019

Make: Model: **Body Style:** KIA Sportage SUV Year: 2005 Registration: CYP646 Reg Expiry: 06 Oct 2019 WoF Expiry: **Odometer: Good No:** 28 Jun 2020 163,718 Kms 19507700 VIN: **Next Service:** KNEJE55186K148405 168000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	drivers seat worn	
Carpets	Average	
Panels	drivers door trim cracked	
Dashboard	fan controls not working	

## **General Comments**

1 remote not working

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Greg Morgan

Evidence of Cam Belt Replacement: No Kms:

Date: 31 May 2019

		N/A	
		1	
~			
~			
<i>V V</i>			
~			
Cooling System  Coolant condition			
•			
•			
Transmission  Operation   ✓			
•			
		~	
~			
~			
Brakes			
~			
~			
depth	of tyre	es)	
3	.0	mm	
3.0		mm	
1.5		mm	
4.0		mm	
	Yes		
~			
~			
~			
		ı	
~			
Operation   Electrical / Accessories			
· ·			
· ·			
· ·			
•			
•			
•			
<b>v</b>			
~			
<b>'</b>			
2	1	1	
2			
2		V	
	3 3 1 4	マ	

I have read and understood this condition guide.

Name: .....

Signature: .....