

Report ID: 56,680 Version: 3 Created: 22 Aug 2019

Make:	Volkswagen	Model:	Touareg	Body Style:	Wagon		Pass	Fail	N/A
Year:	2009	Registration:	HNS269	Reg Expiry:	10 Dec 2019	Engine			
WoF Expiry:	17 Jul 2020	Odometer:	160,050 Kms	Good No:	19508493	Oil level	~		
VIN:	WVGZZZ7LZ8D06867	Next Service:	Just Serviced	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S S	-161-	s	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	•		
D = dent	s bla			The	EII S	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack				$+ \vee$		Clutch	•		~
P = pin dent					게비	CV joints	~		•
* = decals	616			-NL	EIR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S S S S						Performance	~		
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				,	Tyres (lowest observed tread	-	of tyre	(s)
					Left front 4.0 mm				
						Right front	4.	-	mm
						Left rear	4. 8.	-	mm
Canalitian	- Dunin - Dadu Ina	<b>t</b>	2			Right rear			mm
Conditions During Body Inspection: Dry						Spare	0.0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
	<b>j</b>					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation V			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
							<b>v</b>		
General (	Comments					Window winder FR Window winder RL	<b>v</b>		
							<b>v</b>		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only) Number of keys	<b>/</b>		
							2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
				11113.		Reversing camera			~
Inspected by: J Ottesen Date: 07 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....