

Report ID: 19,508,515 Version: 3 12 Jun 2019 Created:

Make:	Holden	Model:	Malibu	Body Style:	Sedan		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	KQS809	Reg Expiry:	23 Aug 2019	Engine	1	i	1
WoF Expiry:	26 Jun 2020	Odometer:	94,099 Kms	Good No:	19508515	Oil level	~		
VIN:	KL3GA6919FB074390	Next Service:	103,580kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for and milaana	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		-0	S D PT S	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	GIE			The	EID S	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack					S	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	s sc PIP			AL.	ELTP IS	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S P W P S P						Performance	~		
			le defects & blemishes			Hand Brake	~		
	pection Comments	1016.301	le delects & blemisnes	inay not be disp	nayed in the diagram		-	ofture	
Right under sill dented Bonnet latch misaligned						<b>Tyres</b> (lowest observed tread depth of tyres)			
	n stone chips					Left front	6		mm
						Right front		7	mm
						Left rear		3	mm
Conditions During Body Inspection: Wet							Right rear 8 mm		
Under Carriage & Under Report Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments Front wheel drive						Suspension			
Front whee	arive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dachher-	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_				]	Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
						_	1		1
Inspected by: Ca Thach Date: 12 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....