

Report ID: 19,508,558 Version: 1 04 Jun 2019 Created:

Make:	Ford	Model:	Courier	Body Style:	Utility		Pass	Fail	N/A
Year:	2004	Registration:	KUR172	Reg Expiry:	31 Jul 2019	Engine			
WoF Expiry:	31 Oct 2019	Odometer:	277,748 Kms	Good No:	19508558	Oil level	~		
VIN:	MNALSFD403W36164	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	DSC	-0	sc sc	-01-	S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SC DIC			715	SD SD	Operation	~		
PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	HIP				74116	CV joints			~
* = decals	sc 916			- No	FID SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant	SC		SC SC		S D SC	Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Rust under deck liner on mudguards. Holes in deck liner. Stonechips on windscreen. RH headlamp needs						Tyres (lowest observed tread depth of tyres)			es)
buffing.					Left front 5 mm				
Screw holes in dash. Scratches on dash and console. Rear seat headrests missing. Wear on RF seat. RF window switch not working on LF window.						Right front	5	5	mm
		window.				Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear			mm
Conditions During Dody inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Both rear a	de seals leaking. Engine	has oil leaks.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Drives ok.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	<		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
•	ming Mechanism:	Cambelt				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 23	34,000	Reversing camera			~
Inspected by: Roger King Date: 04 Jun 2019									
Date: 04 Juli 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....