

Report ID: 19,508,591 Version: 1 03 Jun 2019 Created:

Make:	Holden	Model:	Captiva 5	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JCG578	Reg Expiry:	17 Aug 2019	Engine	1		
WoF Expiry:	21 May 2020	Odometer:	204,431 Kms	Good No:	19508591	Oil level	~		
VIN:	KL3DD2669FB043643	Next Service:	210,000	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	r		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC S S						Operation	~		
PT = paint defect						Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S W						Performance	~		
D. L.L.		Note: son	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tvre	es)
Rear number plate lights not working						Left front 4 mm			
						Right front			mm
						Left rear		6 mm	
Conditions During Pody Inspection						Right rear		6 mm	
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Wear and tear						Head lights	~		
						Tail lights		~	
Carpets	Average					Indicators	~	•	
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	~		
Noose while releasing brake pedal						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)	~	•	
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	2 V		
	uning resi		Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	•								•
Inspected by: Mathew Varghese Date: 03 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....