



This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle has been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	Hatchback
Model:	Demio	VIN:	7AT0C12HX19106871
Year:	2008	Odometer:	95,142 Kms
Road Conditions During Test Drive:	Dry		

Inspected by:	Sudhin Ramachandran	Date:	04 Jun 2019
I have read and understood this condition guide:			
Name:		Signature:	