

Report ID: 19,513,015 Version: 2 26 Jun 2019 Created:

| Make: | Mazda | Model: | Demio | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|------------------------|----------------|------------------------|-------------------|-----------------------|--|--------------------|------|----------|
| Year: | 2006 | Registration: | JZE81 | Reg Expiry: | 14 Oct 2019 | Engine | | | |
| WoF Expiry: | 09 Jul 2020 | Odometer: | 77,822 Kms | Good No: | 19513015 | Oil level | ~ | | |
| VIN: | 7AT0C12HX16439017 | Next Service: | | Service Histor | | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | | с I I | | 1 B 41 1 | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | s w | -0 | S SD | | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | IS GIE | | | The | BIDS | Operation | ~ | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | |
| PT = paint def C = crack | ect M | | | + | | Clutch | V | | ~ |
| P = pin dent | Ho | KI | | | JUII —— | CV joints | ~ | | |
| * = decals | MIK | | | AL- | ELIPS S | Wheel bearings | | | |
| SC = stone chips | | | | | | Wheel bearings | | | |
| W = significant scuffs W S S S C W S | | | | | | | | | |
| | | | | | | Performance | ~ | | <u> </u> |
| Body Ins | pection Comments | Note: son | ne defects & blemishes | s may not be disp | blayed in the diagram | Hand Brake | | | Ļ |
| FL and FR window weather seal worn | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | | .5 | mm |
| | | | | | | Right front | 5 | .5 | mm |
| [| | | | | | Left rear | 4 | .5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5.5 mm | | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| 2WD | | | | | | Suspension performance | | ~ | |
| | | | | | | Steering performance | ~ | | |
| Shor | | | | | | | ~ | | |
| | | | | | | Air Conditioning / Heater | litioning / Heater | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Comoto | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | missing pa | arts from dash | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| Squeezing noise from front suspension | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | r | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | 1 | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | - | | · | | | Remote locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| L | | | | | | | 1 | 1 | |
| Inspected by: Sudhin Ramachandran Date: 26 Jun 2019 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: