

Report ID: 19,514,424 Version: 1 25 Jun 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2009	Registration:	EWZ64	Reg Expiry:	15 Jul 2019	Engine	1		
WoF Expiry:	28 Mar 2020	Odometer:	206,612 Kms	Good No:	19514424	Oil level	~		
VIN:	WF0GXXGBBG8Y7185	Next Service:	218495	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC		S P SC P SC		S SC	Performance	~		
Key:		-0		500-	330	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	Fransmission		
D = dent R = rust	S D SC			215	S SC	Operation	~		
PT = paint defe		r I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~		
* = decals	s sc 916			The second	ALC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	s D SC		P SC P SC		SC	Performance	~		
Podylogr	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front 6 mm			
						Right front	e		mm
						Left rear	3		mm
Conditions During Body Inspection: Dry						Right rear		2 mm	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd some base	is screwed to th	e dash ,			Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	2 V		
Koad Con	ations During Test	Drive:	Dry			Remote locking	~		
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
		•							•
Inspected by: Donovan Matara Date: 25 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: