

Basic Vehicle Condition Guide

Report ID: 19,514,741


Version: 1

Created: 24 Jun 2019

Make: Model: Holden Barina **Body Style:** Hatchback Year: 2012 Registration: **GHY623** Reg Expiry: 07 Aug 2019 **WoF Expiry: Odometer: Good No:** 13 May 2020 89,480 Kms 19514741 VIN: KL3TF48E9CB098294 **Next Service:** 104000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System		ı	
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	•		
Transmission			
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		5	mm
Right front	6		mm
Left rear	6		mm
Right rear	6		mm
Spare			
Suspension			
Suspension performance	\(\times \)		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			1

Signature:

Donovan Matara 24 Jun 2019 Inspected by:

Name: