



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,515,047
Version:	1
Created:	22 Aug 2019

Make:	Mercedes-Benz	Body Style:	Hatchback
Model:	C-Class	VIN:	WDB2037462A879621
Year:	2006	Odometer:	83,062 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release	<input checked="" type="checkbox"/>	Cooling System			Exterior		
1	Battery	<input checked="" type="checkbox"/>	31	Reversing Camera	<input type="checkbox"/>	55	Coolant Condition	<input checked="" type="checkbox"/>	78	Under Carriage	Good
2	Headlights	<input checked="" type="checkbox"/>	32	USB Port	<input type="checkbox"/>	56	Performance	<input checked="" type="checkbox"/>	79	Sun Roof Operation	<input type="checkbox"/>
3	Tail Lights	<input checked="" type="checkbox"/>	33	Window Lock Switch	<input type="checkbox"/>	57	Radiator/Hoses (visual)	<input checked="" type="checkbox"/>	80	Front Windscreen (no chips)	Good
4	High Stop Light	<input checked="" type="checkbox"/>	Transmission and Drive			Suspension			81	Back Windscreen (no chips)	Good
5	Front Right Indicators	<input checked="" type="checkbox"/>	34	Operation	<input checked="" type="checkbox"/>	58	Suspension Performance	<input checked="" type="checkbox"/>	82	Side Windows (no chips)	Good
6	Front Left Indicators	<input checked="" type="checkbox"/>	35	Noise	<input checked="" type="checkbox"/>	59	Steering Performance	<input checked="" type="checkbox"/>	83	Front Wiper Blades	Good
7	Rear Right Indicators	<input checked="" type="checkbox"/>	36	Clutch	<input type="checkbox"/>	60	Shock Absorbers	<input checked="" type="checkbox"/>	84	Rear Wiper Blade	Good
8	Rear Left Indicators	<input checked="" type="checkbox"/>	37	CV Joints	<input type="checkbox"/>	Wheels and Tyres			85	R/H Mirror	Good
9	Reversing Lights	<input checked="" type="checkbox"/>	38	Wheel Bearing	<input checked="" type="checkbox"/>	61	Left Front	7.0 mm	86	L/H Mirror	Good
10	Rear Reflectors	<input checked="" type="checkbox"/>	39	Wheel Balance	<input checked="" type="checkbox"/>	62	Right Front	7.0 mm	87	L/F Guard	Good
11	Hazard Lights	<input checked="" type="checkbox"/>	40	Gearbox (Manual)	<input type="checkbox"/>	63	Left Rear	7.0 mm	88	R/F Guard	Good
12	Courtesy Lights	<input checked="" type="checkbox"/>	41	Engine Timing	Timing Chain	64	Right Rear	7.0 mm	89	L/H Doors	Good
13	Dashboard Lights	<input checked="" type="checkbox"/>	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes	90	R/H Doors	Good
14	Dashboard Dimmer Switch	<input type="checkbox"/>	43	Replaced at (odometer reading)		66	Tools	<input checked="" type="checkbox"/>	91	L/H Sill	Good
15	Number Plate Light	<input checked="" type="checkbox"/>	Brakes			Interior			92	R/H Sill	Good
16	Dashboard Warning Lights	<input checked="" type="checkbox"/>	44	Front Brakes	<input checked="" type="checkbox"/>	67	AC Operation	<input checked="" type="checkbox"/>	93	Boot/Tail Gate	Good
17	Speedo	<input checked="" type="checkbox"/>	45	Rear Brakes	<input checked="" type="checkbox"/>	68	Heater Fan	<input checked="" type="checkbox"/>	94	Front Bumper	Good
18	Odometer	<input checked="" type="checkbox"/>	46	Handbrake	<input checked="" type="checkbox"/>	69	Seatbelts	<input checked="" type="checkbox"/>	95	Rear Bumper	Good
19	Rev Counter	<input checked="" type="checkbox"/>	Keys and Locking			70	Horn	<input checked="" type="checkbox"/>	96	Roof	Good
20	Fuel Gauge	<input checked="" type="checkbox"/>	47	Central Locking	<input checked="" type="checkbox"/>	71	Seat Heaters	<input type="checkbox"/>	97	Bonnet	Good
21	Wipers Front/Rear	<input checked="" type="checkbox"/>	48	Remote Locking	<input checked="" type="checkbox"/>	72	Sun Visors	<input checked="" type="checkbox"/>	98	Fuel Cap	<input checked="" type="checkbox"/>
22	Window Opener FL	<input checked="" type="checkbox"/>	49	Number of Keys	1	73	Sun Visors Lights/Mirrors	<input checked="" type="checkbox"/>	99	Mud Flaps	<input checked="" type="checkbox"/>
23	Window Opener FR	<input checked="" type="checkbox"/>	Engine			74	Seats	Good	100	WOF	<input checked="" type="checkbox"/>
24	Window Opener RL	<input type="checkbox"/>	50	Oil Level	<input checked="" type="checkbox"/>	75	Carpets	Good	Turners Certification Key: ✓ = Pass X = Fail • = Not applicable for this vehicle		
25	Window Opener RR	<input type="checkbox"/>	51	Smokes and Fumes	<input checked="" type="checkbox"/>	76	Panels	Good			
26	Rear View Mirrors	<input checked="" type="checkbox"/>	52	Performance	<input checked="" type="checkbox"/>	77	Dashboard	Good			
27	Radio (Basic Test Only)	<input checked="" type="checkbox"/>	53	Noise	<input checked="" type="checkbox"/>						
28	CD (Basic Test Only)	<input checked="" type="checkbox"/>	54	Starter Motor	<input checked="" type="checkbox"/>						
29	Boot Open Switch	<input checked="" type="checkbox"/>									

Inspected by:	Mathew Varghese	Date:	09 Jun 2019
I have read and understood this condition guide:			
Name:		Signature:	