

Report ID: 19,515,109 Version: 1 11 Jun 2019 Created:

Make:	Toyota	Model:	Vitz	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2005	Registration:	JTB230	Reg Expiry:	14 Jun 2019	Engine				
WoF Expiry:	24 Jun 2020	Odometer:	107,523 Kms	Good No:	19515109	Oil level	~			
VIN:	7AT0H63EX15005644	Next Service:	115,600 kms	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional c	harge.	Coolant condition	~			
	W		SC W	W		Performance	~			
Key:		-0		$\exists (\alpha) =$		Radiator / Hoses (visual	~			
S = scratch D = dent						Transmission	Transmission			
D = dent R = rust	SC DIA			715	HIV SC	Operation	~			
PT = paint defe		FI		$\left[\left(\right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				74 <u>11</u> 1	CV joints	~			
* = decals	sc 916			The second		Wheel bearings	~			
SC = stone chips						Brakes	Brakes			
W = significant scuffs S W W						Performance	~			
Pedular	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
						Left front 5.3 m				
						Right front		5.8	mm	
						Left rear		1.4	mm	
Conditions During Body Inspection: Wet						Right rear		3.8	mm	
Conditions During Body Inspection: Wet						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	e 🖌			
						Steering performance	- ·			
						Shock absorbers	~			
						Air Conditioning / Heato	•		I	
						Operation				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights				
Carpets	Good					Indicators				
Panels	Good					Dashboard warning ligh				
						Wipers (front & rear)				
Dashboa	rd Good					Window winder FL	~			
	I					Window winder FR	- V			
General Comments						Window winder RL	~			
						Window winder RE	- V			
						Rear view mirrors	~			
						Radio (basic test only)				
						CD (basic test only)	~			
						Number of keys	1	I	I	
Road Conditions During Test Drive: Wet						Central locking				
ROAD CON	unions During Test	L DIIVE:	Wet			Remote locking	~			
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	,		~	
	-1	•	1.1							
Inspected by: Ian Dunn Date: 10 Jun 2019										

I have read and understood this condition guide.

Name:

Signature: