

Report ID: 56,698 Version: 2 12 Jul 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A	
Year:	2008	Registration:	EHT830	Reg Expiry:	20 Dec 2019	Engine				
WoF Expiry:	05 Jul 2020	Odometer:	180,082 Kms	Good No:	19515939	Oil level	~			
VIN:	6FPAAAJGAT7U34513	Next Service:	190095	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:	ISC S	-0	SC SC	-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust PT = paint defect						Operation	~			
						Noise	~			
C = crack				+		Clutch			~	
P = pin dent						CV joints	~		-	
* = decals	sc 916		<u> </u>	- AL	ETTPS-	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC S S S S S S S S S S S S S S S S S S						Performance	~			
		Note: son	ne defects & blemishes	may not be disr		Hand Brake	~			
	pection Comments	Note: 3011	le delects & blemsnes	s may not be disp	nayed in the diagram			ofture		
Minor oil leaks						Tyres (lowest observed tread depth of tyres)				
						Left front		.0	mm	
						Right front		.0	mm	
						Left rear	4		mm	
Conditions During Body Inspection: Dry						Right rear	4.0 mm			
Under Comiene & Under Deurset here estime Comments						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Comoto	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~		1	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~		+	
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	+		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
	•		••							
Inspected by: Chris Date: 14 Jun 2019										

I have read and understood this condition guide.

Name:

Signature: