

Basic Vehicle Condition Guide

Report ID: 19,516,360

Pass

1

~

V

V

1

J

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

11 Jun 2019 Created:

Fail

N/A

mm

mm

mm

mm

6.0

5.9

4.9

5.0

1

1

/

1

1

2

1


1

Yes

Make: Alfa Romeo Model: 147 **Body Style:** Hatchback Year: 2002 Registration: AWA839 **Reg Expiry:** 16 Aug 2019 WoF Expiry: **Odometer:** 05 Apr 2020 177,122 Kms **Good No:** 19516360 VIN: ZAR93700003071904 Next Service: ? **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Crack in right front indicator lens.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil weep commensurate with age and kms of vehicle

Interior Comments		
Seats	Average	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Engine oil level is below the low mark on engine dip stick. One of key remotes are not working to lock & unlock vehicle. Left side air bag cover has broken away from it's clips that hold it in place.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** Kms: No

I have read and understood this condition guide.

Date: 10 Jun 2019 Inspected by: Jason Young

Name:	Signature: