

Report ID: 19,516,817 Version: 1 10 Jun 2019 Created:

Make:	Nissan	Model:	March	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2002	Registration:	GBY280	Reg Expiry:	12 Aug 2019	Engine		-		
WoF Expiry:	05 Sep 2019	Odometer:	114,462 Kms	Good No:	19516817	Oil level	~			
VIN:	7AT0DH0KX11051717	Next Service:		Service Histor		Smoke & fumes	~			
						Performance	~			
	port is not a warranty		C 1 1		1 12 11 1	Noise	•	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	s w	-0	SD SD		S D	Radiator / Hoses (visual)	~		<u> </u>	
S = scratch						Transmission				
D = dent	scw 6/6			The	EID S	Operation	~			
R = rust PT = paint def				r In	JHIH	Noise	~			
C = crack				+	SC	Clutch	•		~	
P = pin dent						CV joints	~		-	
* = decals	s sc PIP			AL.	EIP s	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S W S D PT S D PT W S R PT						Performance	~		1	
		Note: som	ne defects & blemishes	may not be disr		Hand Brake	~			
	pection Comments			indy not be disp	ayea in the diagram			oftyre	<u> </u>	
Aerial worn Front bumper alignment						Tyres (lowest observed tread depth of tyres) Left front 4 mm				
i i one burn,						Right front			mm	
						Left rear		5	mm	
							•		mm	
Conditions During Body Inspection: Dry						Right rear	5 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes			
Key locks all doors but doesn't unlock left rear door						Suspension				
Right rear s	hock leaking					· · ·	~			
Radiator su	pport rusted					Steering performance	~		<u> </u>	
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
stained driver seat worn					Electrical / Accessories					
Seats						Head lights	~			
Carpets	Average					Tail lights	~		<u> </u>	
	Average					Indicators	~		<u> </u>	
Panels	Average					Dashboard warning lights	~		<u> </u>	
Dashboa	screw hole	5				Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~		<u> </u>	
Concrol	-ommonts					Window winder FR		~	<u> </u>	
General Comments Pulleys noisy					Window winder RL	~				
i uncys nots	· ,					Window winder RR	~		<u> </u>	
						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~		 	
						CD (basic test only)	~			
[Number of keys	2			
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>	
Enging Ti	ming Machanism	Timina	[°] hain			Remote locking	~		<u> </u>	
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspecte	d by: John Lindsay					Date: 10 Jun 20	9			
inspecte						Bate. 10 Juli 20	-			

I have read and understood this condition guide.

Name:

Signature: