

Report ID: 19,516,872


Version: 1

Created: 13 Jun 2019

Make:	Isuzu	Model:	Bighorn	Body Style:	Wagon
Year:	1994	Registration:	BLN240	Reg Expiry:	22 Sep 2019
WoF Expiry:	15 Nov 2019	Odometer:	335,054 Kms	Good No:	19516872
VIN:	7A897130703102310	Next Service:	315;000	Service Histor	r y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left rear tail light broken

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Large engine oil leak

Interior Commen	<u>ts</u>
Seats	drivers seat ripped otherwise good
Carpets	Average
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Date: 12 Jun 2019 Inspected by: lan Dunn

		1	Т
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	es)
Left front	6	.1	mm
Right front	6.5		mm
Left rear	2	.2	mm
Right rear	2.4		mm
Spare		Yes	
Suspension			
Suspension performance	v v		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories		_	<u> </u>
Head lights	·/		
Tail lights	· ·		
Indicators	•		
Dashboard warning lights		~	
		•	
Wipers (front & rear) Window winder FL	V		
	-		
Window winder FR	<i>V</i>		
Window winder RL			<i>V</i>
Window winder RR			-
Rear view mirrors	-		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking		~	
Remote locking			~
Sat. Nav. (basic test only)			~
Reversing camera	~		

I have read and understood this condition guide.

Name:

Signature: